



Ref: US.000173

6th March 2008

To FCC

BABT Balfour House, Churchfield Road Walton on Thames Surrey, KT12 4TD United Kingdom Telephone: +44 (0)1932 251200 Fax: +44 (0)1932 251201

Direct Dial: +44 (0)1932 251230 E-mail: Tom.Twynam@babt.com Website: www.babt.com

Evaluation of Loc8tor Lite Handheld FCC id: TUW-SYC1

I have assessed the above referenced submission for the Loc8tor Handheld and found it to be compliant.

The following were noted and resolved during the evaluation.

1. Test Results

A number of clarifications were requested concerning the test report, these were all addressed and the report re-issued.

2. RF Exposure

It was confirmed that the device is categorically excluded from routine evaluation and below the low threshold.

3. Label

The original label did not give the name of the product. A new label was provided which included the product name.

4. Agents Letters

Initially these letters only nominated the companies involved and not individuals within the organisations. Further letters were obtained to correct this problem.

Yours sincerely

Tom Twynam Technical Certifier For BABT TCB

T.J. Twynan