External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214 Tes

Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA

Model: RBGrooveA-52HPn-US

Test #: 170104


4 Test to: 47CFR, 15.407, RSS-247 File: RBGrooveA-52HPn US ExtPho

S/N: 27895

FCC ID: TV7GRV-A52HPN IC: 7442A-GRVA52HPN

Date: April 17, 2017

Page 1 of 5





Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RBGrooveA-52HPn-US

Test #: 170104


Test to: 47CFR, 15.407, RSS-247 File: RBGrooveA-52HPn US ExtPho


S/N: 27895

FCC ID: TV7GRV-A52HPN IC: 7442A-GRVA52HPN

Date: April 17, 2017

Page 2 of 5





Phone/Fax: (913) 837-3214 Revision 1 Fil Mikrotikls SIA

Model: RBGrooveA-52HPn-US Test #: 170104

Test to: 47CFR, 15.407, RSS-247

File: RBGrooveA-52HPn US ExtPho

S/N: 27895

FCC ID: TV7GRV-A52HPN IC: 7442A-GRVA52HPN

Date: April 17, 2017

Page 3 of 5





Revision 1

Phone/Fax: (913) 837-3214

Mikrotikls SIA

Model: RBGrooveA-52HPn-US

Test #: 170104

Test to: 47CFR, 15.407, RSS-247 File: RBGrooveA-52HPn US ExtPho

S/N: 27895

FCC ID: TV7GRV-A52HPN IC: 7442A-GRVA52HPN

Date: April 17, 2017

Page 4 of 5



Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RBGrooveA-52HPn-US

Test #: 170104

Test to: 47CFR, 15.407, RSS-247 File: RBGrooveA-52HPn US ExtPho

S/N: 27895

FCC ID: TV7GRV-A52HPN IC: 7442A-GRVA52HPN

Date: April 17, 2017

Page 5 of 5