Internal photographs of equipment under test (shield in place)



Shield removed for photograph



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RB751U-2HnD Test #: 110802

Test to: CFR47 (15.247) File: IntPho RB751U2HnD SN: 2B67011CE826 FCC ID#: TV7RB751-2HND Date: August 29, 2011

Page 1 of 2

Back side of EUT PCB (heat sink in place – No components placed under heat sink)



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RB751U-2HnD Test #: 110802

Test to: CFR47 (15.247) File: IntPho RB751U2HnD SN: 2B67011CE826 FCC ID#: TV7RB751-2HND

Date: August 29, 2011

Page 2 of 2