

Internal photographs of equipment under test component side with shields in place (top)



Internal photographs of equipment under test component side with shields removed (top)



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214


Revision 1

Mikrotikls SIA Model: RBSXTG-2HnD Test #: 120716

Test to: CFR47 (15.247) File: IntPho RBSXTG 2HND SN: 399501DD0C31 FCC ID#: TV7SXTG-2HND Date: August 15, 2012

Page 1 of 2

Internal photographs of equipment under test (inside enclosure), bottom side PCB with antenna



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBSXTG-2HnD Test #: 120716

Test to: CFR47 (15.247) File: IntPho RBSXTG 2HND SN: 399501DD0C31 FCC ID#: TV7SXTG-2HND Date: August 15, 2012

Page 2 of 2