

## External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R11e-5HnD Test #: 190204


Test to: 47CFR, 15.407, RSS-247 File: R11E5HM ExtPho

S/N: 8EDB09784363/632/r2


FCC ID: TV7R11E5HM IC: 7442A- R11E5HND Date: February 27, 2019

Page 1 of 2

EUT placed on support interface board



Support interface board



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: R11e-5HnD Test #: 190204

Test to: 47CFR, 15.407, RSS-247 File: R11E5HM ExtPho

S/N: 8EDB09784363/632/r2

FCC ID: TV7R11E5HM IC: 7442A- R11E5HND Date: February 27, 2019

Page 2 of 2