Internal photographs of equipment under test Internal photographs of equipment under test (inside enclosure)





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: R5SHPn Test #: 110826M Test to: CFR47 (15.247) File: IntPho R5SHPn

SN: 2B7301BF7D81 FCC ID#: TV7R5SHPN Date: September 26, 2011

Page 1 of 4

Bottom side of supporting circuit board



EUT PCB (heat sink in place)



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: R5SHPn Test #: 110826M Test to: CFR47 (15.247) File: IntPho R5SHPn

SN: 2B7301BF7D81 FCC ID#: TV7R5SHPN Date: September 26, 2011

Page 2 of 4



Heat sink removed top side



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Revision 1

Mikrotikls SIA Model: R5SHPn Test #: 110826M Test to: CFR47 (15.247) File: IntPho R5SHPn

SN: 2B7301BF7D81 FCC ID#: TV7R5SHPN Date: September 26, 2011

Page 3 of 4

Heat sink removed bottom side



Shield removed for photograph



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-32

Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R5SHPn Test #: 110826M Test to: CFR47 (15.247) File: IntPho R5SHPn

SN: 2B7301BF7D81 FCC ID#: TV7R5SHPN Date: September 26, 2011

Page 4 of 4