External photographs of equipment under test





Model: RouterBOARD 912R-2nD-LTm

Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

053 Test #: 171228 637-3214 Test to: 47CFR 15.247, RSS-247

Mikrotikls SIA


Phone/Fax: (913) 837-3214 Test to: 47CFR 15.247, Facilities Revision 1 File: RB912R2NDLTM ExtPho


S/N: 27895

FCC ID: TV7RB912R-2NDLTM IC: 7442A-912R2NDLTM

Date: February 21, 2018

Page 1 of 4





Model: RouterBOARD 912R-2nD-LTm

Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg KS 66053

Louisburg, KS 66053 Test #: 171228

Phone/Fax: (913) 837-3214 Test to: 47CFR 15.247, RSS-247 Revision 1 File: RB912R2NDLTM ExtPho

Mikrotikls SIA

S/N: 27895

FCC ID: TV7RB912R-2NDLTM IC: 7442A-912R2NDLTM

Date: February 21, 2018

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Model: RouterBOARD 912R-2nD-LTm Test #: 171228

Mikrotikls SIA

S/N: 27895 FCC ID: TV7RB912R-2NDLTM IC: 7442A-912R2NDLTM Date: February 21, 2018

Page 3 of 4





Model: RouterBOARD 912R-2nD-LTm

Rogers Labs, Inc. 4405 W. 259th Terrace

Louisburg, KS 66053 Test #: 171228 Phone/Fax: (913) 837-3214 Test to: 47CF

Phone/Fax: (913) 837-3214 Test to: 47CFR 15.247, RSS-247 Revision 1 File: RB912R2NDLTM ExtPho

Mikrotikls SIA

S/N: 27895

FCC ID: TV7RB912R-2NDLTM IC: 7442A-912R2NDLTM

Date: February 21, 2018

Page 4 of 4