
Internal photographs of equipment under test



Shield in place



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Revision 1

Mikrotikls SIA Models: RBSXT5HacD2n-US Test #: 160823


Test to: CFR47 (15.247) File: RBSXT5HacD2n IntPho S/N: 5E7801DDBBE0/522 FCC ID: TV7SXT5HACD2N IC: 7442A-SXT5HACD2N Date: October 13, 2016

Page 1 of 4

Close up of transmitters



5 GHz antenna



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053


Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Models: RBSXT5HacD2n-US Test #: 160823

Test to: CFR47 (15.247) File: RBSXT5HacD2n IntPho S/N: 5E7801DDBBE0/522 FCC ID: TV7SXT5HACD2N IC: 7442A-SXT5HACD2N Date: October 13, 2016

Page 2 of 4




Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Models: RBSXT5HacD2n-US Test #: 160823

Test to: CFR47 (15.247) File: RBSXT5HacD2n IntPho S/N: 5E7801DDBBE0/522 FCC ID: TV7SXT5HACD2N IC: 7442A-SXT5HACD2N Date: October 13, 2016

Page 3 of 4



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Models: RBSXT5HacD2n-US Test #: 160823

Test to: CFR47 (15.247) File: RBSXT5HacD2n IntPho S/N: 5E7801DDBBE0/522 FCC ID: TV7SXT5HACD2N IC: 7442A-SXT5HACD2N Date: October 13, 2016

Page 4 of 4