External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBwAP-2nD Test #: 151031


Test to: 47CFR 15.247, RSS-247

File: RBwAP2nD ExtPho

S/N: 551501D0E8C

FCC ID#: TV7RBWAP2ND IC: 7442A-RBWAP2ND Date: December 7, 2015

Page 1 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBwAP-2nD Test #: 151031

Test to: 47CFR 15.247, RSS-247

File: RBwAP2nD ExtPho

S/N: 551501D0E8C

FCC ID#: TV7RBWAP2ND IC: 7442A-RBWAP2ND Date: December 7, 2015

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214 Revision 1

Mikrotikls SIA Model: RBwAP-2nD Test #: 151031

Test to: 47CFR 15.247, RSS-247 File: RBwAP2nD ExtPho

S/N: 551501D0E8C

FCC ID#: TV7RBWAP2ND IC: 7442A-RBWAP2ND Date: December 7, 2015

Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBwAP-2nD Test #: 151031

File: RBwAP2nD ExtPho

Test to: 47CFR 15.247, RSS-247

S/N: 551501D0E8C

FCC ID#: TV7RBWAP2ND IC: 7442A-RBWAP2ND Date: December 7, 2015

Page 4 of 4