Internal photographs of equipment under test With shields



Shields removed



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Revision 1

Mikrotikls SIA S/N: 54EE04337EEF


Model: RB953GS-5HnT-RP-US FCC ID: TV7RB953GS5HNTM Test #: 170316 IC: 7442A-RB953GS5HNT

Test to: 47CFR, 15.407, RSS-247 Date: April 3, 2017 File: RB953GS-5HnT-RP-US FCC IntPho Page 1 of 3

Back side of module with heat sink



Back side of module with heat sink removed



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA S/N: 54EE04337EEF

Model: RB953GS-5HnT-RP-US FCC ID: TV7RB953GS5HNTM

Test #: 170316 IC: 7442A-RB953GS5HNT Test to: 47CFR, 15.407, RSS-247 Date: April 3, 2017

File: RB953GS-5HnT-RP-US FCC IntPho Page 2 of 3

Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA S/N: 54EE04337EEF

Model: RB953GS-5HnT-RP-US FCC ID: TV7RB953GS5HNTM Test #: 170316 IC: 7442A-RB953GS5HNT

Test to: 47CFR, 15.407, RSS-247 Date: April 3, 2017 File: RB953GS-5HnT-RP-US FCC IntPho Page 3 of 3