## Test setup photographs





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Revision 1

Mikrotikls SIA Model: RBmAP L-2nD Test #: 150730A-151104

Test to: 47CFR 15.247, RSS-247 File: RBmAPL2ND TSup

S/N: 642A01DDE062 FCC ID#: TV7MAPL2ND IC: 7442A-MAPL2ND Date: December 20, 2015

Page 1 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBmAP L-2nD Test #: 150730A-151104

Test to: 47CFR 15.247, RSS-247 File: RBmAPL2ND TSup

S/N: 642A01DDE062 FCC ID#: TV7MAPL2ND IC: 7442A-MAPL2ND Date: December 20, 2015

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBmAP L-2nD

Test #: 150730A-151104

Test to: 47CFR 15.247, RSS-247 File: RBmAPL2ND TSup

S/N: 642A01DDE062 FCC ID#: TV7MAPL2ND IC: 7442A-MAPL2ND Date: December 20, 2015

Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBmAP L-2nD

Test #: 150730A-151104

Test to: 47CFR 15.247, RSS-247 File: RBmAPL2ND TSup

S/N: 642A01DDE062 FCC ID#: TV7MAPL2ND IC: 7442A-MAPL2ND Date: December 20, 2015

Page 4 of 4