

## Test setup photographs

## **AC Line Conducted Emissions**





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RouterBOARD 953GS-5HnT

Test #: 140605

Test to: CFR47 (15.247) File: TSup RB953GS5HnT SN: 49C5028C45D2/421 FCC ID#: TV7RB953GS-5HNT

Date: June 30, 2014

Page 1 of 4

## **Radiated Emissions**





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RouterBOARD 953GS-5HnT

Test #: 140605


Test to: CFR47 (15.247) File: TSup RB953GS5HnT

SN: 49C5028C45D2/421 FCC ID#: TV7RB953GS-5HNT

Date: June 30, 2014

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RouterBOARD 953GS-5HnT

Test #: 140605

Test to: CFR47 (15.247) File: TSup RB953GS5HnT SN: 49C5028C45D2/421 FCC ID#: TV7RB953GS-5HNT

Date: June 30, 2014

Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RouterBOARD 953GS-5HnT

Test #: 140605

Test to: CFR47 (15.247) File: TSup RB953GS5HnT SN: 49C5028C45D2/421 FCC ID#: TV7RB953GS-5HNT

Date: June 30, 2014

Page 4 of 4