

External photographs of equipment under test







Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R11e-5HacD Test #: 181029

Test to: 47CFR, 15.407, RSS-247 File: ExtPho R11e5HacD

S/N: 8EDC0800A953/814/r2 FCC ID: TV7R11E5HAM IC: 7442A-R11E5HAM -247 Date: January 22, 2019

Page 1 of 4







Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R11e-5HacD Test #: 181029

Test to: 47CFR, 15.407, RSS-247 File: ExtPho R11e5HacD

S/N: 8EDC0800A953/814/r2 FCC ID: TV7R11E5HAM IC: 7442A-R11E5HAM -247 Date: January 22, 2019

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R11e-5HacD Test #: 181029

Test to: 47CFR, 15.407, RSS-247 File: ExtPho R11e5HacD

S/N: 8EDC0800A953/814/r2 FCC ID: TV7R11E5HAM IC: 7442A-R11E5HAM S-247 Date: January 22, 2019

Page 3 of 4

EUT placed on support interface board



Support interface board



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R11e-5HacD Test #: 181029

Test to: 47CFR, 15.407, RSS-247 File: ExtPho R11e5HacD

S/N: 8EDC0800A953/814/r2 FCC ID: TV7R11E5HAM IC: 7442A-R11E5HAM -247 Date: January 22, 2019

Page 4 of 4