

## External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Revision 1


Mikrotikls SIA Model: RB951G-2HnD Test #: 120910

Test to: CFR47 (15.247) File: ExtPho RB951G2HnD SN: 3B6C023FB1B6

FCC ID#: TV7RB951G-2HND Date: February 12, 2013

Page 1 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1


Mikrotikls SIA Model: RB951G-2HnD Test #: 120910

Test to: CFR47 (15.247) File: ExtPho RB951G2HnD SN: 3B6C023FB1B6

FCC ID#: TV7RB951G-2HND

Date: February 12, 2013

Page 2 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RB951G-2HnD Test #: 120910

Test to: CFR47 (15.247) File: ExtPho RB951G2HnD SN: 3B6C023FB1B6

FCC ID#: TV7RB951G-2HND

Date: February 12, 2013

Page 3 of 3