
External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214 Revision 1

Mikrotikls SIA Model: RB952Ui-5ac2nD-US

Test #: 160414d


Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB952Ui-5ac2nD ExtPho


S/N: 5EB204A373B8/516 FCC ID#: TV7RB952-5AC2ND

IC: 7442A-9525AC

Date: July 27, 2016

Page 1 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RB952Ui-5ac2nD-US

Test #: 160414d


Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB952Ui-5ac2nD ExtPho


S/N: 5EB204A373B8/516 FCC ID#: TV7RB952-5AC2ND

IC: 7442A-9525AC

Date: July 27, 2016

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

1.4

Mikrotikls SIA Model: RB952Ui-5ac2nD-US

Test #: 160414d

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB952Ui-5ac2nD ExtPho

S/N: 5EB204A373B8/516 FCC ID#: TV7RB952-5AC2ND

IC: 7442A-9525AC

RSS-247 Date: July 27, 2016

Page 3 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RB952Ui-5ac2nD-US

Test #: 160414d

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB952Ui-5ac2nD ExtPho

S/N: 5EB204A373B8/516 FCC ID#: TV7RB952-5AC2ND

IC: 7442A-9525AC

RSS-247 Date: July 27, 2016

Page 4 of 4