
External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RouterBOARD 912G-5HPnD

Test #: 120926


Test to: 47CFR, 15.247 File: ExtPho RB912G5HPnD SN: 3C5701DDDA18

FCC ID#: TV7RB912G-5HPND

Date: October 17, 2012

Page 1 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA

Model: RouterBOARD 912G-5HPnD

Test #: 120926

Test to: 47CFR, 15.247 File: ExtPho RB912G5HPnD SN: 3C5701DDDA18

FCC ID#: TV7RB912G-5HPND

Date: October 17, 2012 Page 2 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RouterBOARD 912G-5HPnD

Test #: 120926

Test to: 47CFR, 15.247 File: ExtPho RB912G5HPnD SN: 3C5701DDDA18

FCC ID#: TV7RB912G-5HPND

Date: October 17, 2012 Page 3 of 3