

Internal photographs of equipment under test PCB with shield



Shield removed for photograph



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Mikrotikls SIA Model: OmniTik U-5HnD Test #: 110518 Test to: FCC (15.247) File: IntPho OmniTik

FCC ID#: TV7OMNITIKUPA5HND SN: 294601DD2011 Date: June 24, 2011 Page 1 of 2

Back side of EUT PCB



Heat sink removed



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Mikrotikls SIA Model: OmniTik U-5HnD Test #: 110518 Test to: FCC (15.247) File: IntPho OmniTik

FCC ID#: TV7OMNITIKUPA5HND SN: 294601DD2011 Date: June 24, 2011 Page 2 of 2