
Test setup photographs





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1


Mikrotikls SIA Model: RB951Ui-2nD

Test #: 150901

Test to: CFR47 (15.247) File: RB951Ui2nD TSup S/N: 5D4501DDA4E7/527 FCC ID#: TV7RB951UI-2ND

IC: 7442A-9512ND Date: October 13, 2015

Page 1 of 5





Revision 1

Mikrotikls SIA Model: RB951Ui-2nD

Test #: 150901

Test to: CFR47 (15.247) File: RB951Ui2nD TSup S/N: 5D4501DDA4E7/527 FCC ID#: TV7RB951UI-2ND

IC: 7442A-9512ND Date: October 13, 2015

Page 2 of 5





Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: RB951Ui-2nD Test #: 150901

Test to: CFR47 (15.247) File: RB951Ui2nD TSup S/N: 5D4501DDA4E7/527 FCC ID#: TV7RB951UI-2ND

IC: 7442A-9512ND Date: October 13, 2015

Page 3 of 5





Revision 1

Mikrotikls SIA Model: RB951Ui-2nD

Test #: 150901

Test to: CFR47 (15.247) File: RB951Ui2nD TSup S/N: 5D4501DDA4E7/527 FCC ID#: TV7RB951UI-2ND

IC: 7442A-9512ND Date: October 13, 2015

Page 4 of 5

Revision 1

Mikrotikls SIA Model: RB951Ui-2nD

Test #: 150901

Test to: CFR47 (15.247) File: RB951Ui2nD TSup S/N: 5D4501DDA4E7/527 FCC ID#: TV7RB951UI-2ND

IC: 7442A-9512ND Date: October 13, 2015

Page 5 of 5