

## External photographs of equipment under test






Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R11e-5HacD Test #: 140610

Test to: CFR47 (15.247) File: ExtPho R11e5HacD SN: 3F1E04E68BEF/001 FCC ID#: TV7R11E5HACD

Date: July 3, 2014 Page 1 of 3

## EUT placed on support interface board



Support interface board (back side)



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: R11e-5HacD Test #: 140610

Test to: CFR47 (15.247) File: ExtPho R11e5HacD SN: 3F1E04E68BEF/001 FCC ID#: TV7R11E5HACD

Date: July 3, 2014 Page 2 of 3

## AC Adapter





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Phone/Fax: (913) 837-32 Revision 1 Mikrotikls SIA Model: R11e-5HacD Test #: 140610

Test to: CFR47 (15.247) File: ExtPho R11e5HacD SN: 3F1E04E68BEF/001 FCC ID#: TV7R11E5HACD

Date: July 3, 2014 Page 3 of 3