
External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: R52HnD Test #: 160720

Test to: 47CFR, 15.247, 15.407, RSS-247

File: R52HnD ExtPho


S/N: 26114

FCC: TV7R52HND IC: 7442A-R52HND Date: August 24, 2016

Page 1 of 3

Support interface board with EUT mounted





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Phone/Fax: (913) 837-3214 Revision 1 Mikrotikls SIA Model: R52HnD Test #: 160720

Test to: 47CFR, 15.247, 15.407, RSS-247


File: R52HnD ExtPho


S/N: 26114

FCC: TV7R52HND IC: 7442A-R52HND Date: August 24, 2016

Page 2 of 3

Support interface board





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: R52HnD Test #: 160720

Test to: 47CFR, 15.247, 15.407, RSS-247

File: R52HnD ExtPho

S/N: 26114

FCC: TV7R52HND IC: 7442A-R52HND Date: August 24, 2016

Page 3 of 3