External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBcAP2nD Test #: 160714

Test to: 47CFR 15.247, RSS-247 File: RBcAP2nD ExtPho

S/N: 69FE01DC4C2C/611 FCC ID#: TV7RBCM2ND

IC: 7442A-CM2ND Date: August 3, 2016

Page 1 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBcAP2nD Test #: 160714


Test to: 47CFR 15.247, RSS-247 File: RBcAP2nD ExtPho

S/N: 69FE01DC4C2C/611 FCC ID#: TV7RBCM2ND

IC: 7442A-CM2ND Date: August 3, 2016

Page 2 of 4





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBcAP2nD Test #: 160714

Test to: 47CFR 15.247, RSS-247

File: RBcAP2nD ExtPho

S/N: 69FE01DC4C2C/611 FCC ID#: TV7RBCM2ND

IC: 7442A-CM2ND Date: August 3, 2016

Page 3 of 4



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA Model: RBcAP2nD Test #: 160714

Test to: 47CFR 15.247, RSS-247 File: RBcAP2nD ExtPho

S/N: 69FE01DC4C2C/611 FCC ID#: TV7RBCM2ND

IC: 7442A-CM2ND Date: August 3, 2016

Page 4 of 4