
Internal photographs of equipment under test



Solder side PCB (Heat sink removed)



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA S/N: 63ED036BBC5F/601 / D0201000000/522


Model: RB921GS-5HPacD-US FCC ID: TV7RB921G-5HPACD

Test #: 170327 IC: 7442A-921G5HPACD

Test to: 47CFR, 15.407, RSS-247 Date: May 10, 2017

File: RB921GS-5HPacD-US IntPho1Page 1 of 4

15S antenna system





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1


Mikrotikls SIA S/N: 63ED036BBC5F/601 / D0201000000/522


Model: RB921GS-5HPacD-US FCC ID: TV7RB921G-5HPACD

IC: 7442A-921G5HPACD Test #: 170327

Test to: 47CFR, 15.407, RSS-247 Date: May 10, 2017 File: RB921GS-5HPacD-US IntPho1Page 2 of 4

## 19S antenna





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214


Revision 1

Mikrotikls SIA S/N: 63ED036BBC5F/601 / D0201000000/522

Model: RB921GS-5HPacD-US FCC ID: TV7RB921G-5HPACD

Test #: 170327 IC: 7442A-921G5HPACD

Test to: 47CFR, 15.407, RSS-247 Date: May 10, 2017 File: RB921GS-5HPacD-US IntPho1Page 3 of 4



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

 $Mikrotikls \ SIA \ S/N: \ 63ED036BBC5F/601 \ / \ D0201000000/522$ 

Model: RB921GS-5HPacD-US FCC ID: TV7RB921G-5HPACD

Test #: 170327 IC: 7442A-921G5HPACD Test to: 47CFR, 15.407, RSS-247 Date: May 10, 2017

File: RB921GS-5HPacD-US IntPho1Page 4 of 4