



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 67 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 68 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 69 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 70 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 71 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









Page No. : 72 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019





Report No. : EP931106




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 73 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019




Report No.: EP931106




TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 74 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019






Report No.: EP931106




TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 75 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019





Report No.: EP931106




SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 76 of 110

EP Report Version : Rev. 01

Issued Date : May 24, 2019









Page No. : 77 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 78 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 79 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 80 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019






Report No. : EP931106




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 81 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 82 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








Page No. : 83 of 110


EP Report Version : Rev. 01

Issued Date : May 24, 2019






Report No.: EP931106



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 84 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019







Report No.: EP931106



TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 85 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 86 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 87 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








Page No. : 88 of 110

EP Report Version : Rev. 01

Issued Date : May 24, 2019








Page No. : 89 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








Page No. : 90 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 91 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









Page No. : 92 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









Page No. : 93 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









Page No. : 94 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








Page No. : 95 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








Page No. : 96 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019





Report No.: EP931106




SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 97 of 110

EP Report Version : Rev. 01

Issued Date : May 24, 2019








TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 98 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








Page No. : 99 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 100 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019








TEL: 886-3-327-3456 FAX: 886-3-327-0973
 Page No.
 : 101 of 110

 EP Report Version : Rev. 01

 Issued Date : May 24, 2019








Page No. : 102 of 110
EP Report Version : Rev. 01
Issued Date : May 24, 2019







 Page No.
 : 103 of 110

 EP Report Version
 : Rev. 01

 Issued Date
 : May 24, 2019