


Appendix H Test Photos



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



Test Photos Appendix H



Side view

SPORTON INTERNATIONAL INC. Page No. : H2 of H4

TEL: 886-3-327-3456 FAX: 886-3-327-0973 751119



Test Photos Appendix H

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973




Test Photos Appendix H

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973