



Appendix E **Test Photos**

1. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz

Internal Antenna



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973



Test Photos Appendix E

For radiated emissions above 1GHz

Internal Antenna



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



Appendix E **Test Photos**

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz

External Antenna



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973



Test Photos Appendix E

For radiated emissions above 1GHz

External Antenna



Front view



Rear view

——THE END——

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page number

: E4 of E4

931106-01