


Appendix I Test Photos



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



Test Photos Appendix I



Side view

SPORTON INTERNATIONAL INC. Page No. : 12 of 14

751119

TEL: 886-3-327-3456 FAX: 886-3-327-0973



Test Photos Appendix I

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.


: I3 of I4

751119




Test Photos Appendix I

## For radiated emissions above 1GHz



## Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973