Report No. : EP790613-01

FortiAP-224E





TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018





Report No.: EP790613-01



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018





Report No.: EP790613-01

Power Cable



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018





Ground Wire



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 31 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018

PoE Adapter: PD-9001GR/AC


(The PoE is for testing only and is not an accessory.)





TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 32 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 33 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 34 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018

For PoE Adapter Power Cable

(The PoE is for testing only and is not an accessory.)





TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 35 of 35
EP Report Version : Rev. 01
Issued Date : Jan. 19, 2018