

1. Photographs of Conducted Emissions Test Configuration

Mode 2





Front view



Rear view

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973


Page No.

: F1 of F15

Report No.

: 6O1926





Side view


 SPORTON INTERNATIONAL INC.
 Page No.
 : F2 of F15

 TEL: 886-3-327-3456
 Report No.
 : 601926

FAX: 886-3-327-0973



# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No.


: F3 of F15 : 6O1926



## For radiated emissions 30MHz~1GHz Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No.


: F4 of F15 : 601926



#### Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.


: F5 of F15

Report No.


: 601926



#### Mode 3



Front view




Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No. : F6 of F15 : 6O1926



#### Mode 4



Front view




Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No. : F7 of F15 : 6O1926



#### Mode 5



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.


: F8 of F15

Report No.


: 601926



#### Mode 6



Front view




Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No. : F9 of F15 : 6O1926



#### Mode 7



Front view




Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No. : F10 of F15 : 6O1926



#### Mode 8



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No.

: F11 of F15 : 601926

Report No.



### For radiated emissions above 1GHz Mode 1



Front view



Rear view


SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973


Page No. Report No. : F12 of F15 : 6O1926



#### Mode 2



Front view




Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report No. : F13 of F15 : 6O1926



#### Mode 3



Front view



Rear view


SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973


Page No. Report No. : F14 of F15 : 6O1926



#### Mode 4



Front view



Rear view

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. Report No. : F15 of F15 : 6O1926