

Appendix H Test Photos

1. Photographs of Conducted Emissions Test Configuration Internal Antenna






Front view



Side view

SPORTON INTERNATIONAL INC.





Under table view

SPORTON INTERNATIONAL INC.

FAX: 886-3-327-0973

TEL: 886-3-327-3456



External Antenna




Front view



Side view

SPORTON INTERNATIONAL INC.





Under table view


SPORTON INTERNATIONAL INC. Page number : H4 of H8




Appendix H **Test Photos**

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz

Internal Antenna



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page number


: H5 of H8

931106



For radiated emissions above 1GHz





Front view



Rear view

SPORTON INTERNATIONAL INC.



Appendix H **Test Photos**

3. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz

External Antenna



Front view




Rear view

SPORTON INTERNATIONAL INC.



For radiated emissions above 1GHz

External Antenna



Front view



Rear view

——THE END——

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page number

: H8 of H8

931106