Appendix A

Non-Conformities for US Radio Equipment Authorization

Non-Conformities FCC ID: TVQ-U24A (Ref # E06-000198-1)

The items listed below represent requests for information following review of this application. Further question may arise pending review of responses to these items.

OK	#	Non-Conformity or Comment	Submitted Response	Respondent / Date of Response
	1	Please contact Syed and explain to him that Application Letters can not be held confidential by the FCC.	Revised confidentiality letter and application letter have been uploaded.	Mary Ellen/8/9/2006
		Currently, his application letter contains a block diagram, some information that appears to be operational in description, and a LMA letter.		
		He will need a letter describing his Limited Modular Approval by itself and it should not have anything confidential in it.		
		So, at minimum, he will need to provide us with a new confidential letter stating that he is holding the operational description and schematics as permanently confidential.		
		He can request that his block diagram be held permanently confidential also.		
	2	Please explain how you arrived at the specific power output for the different antennas that were used.	A revised test report has been uploaded.	Mary Ellen/8/9/2006
	3	Please provide the existing schematics for the unit.	Schematics have been uploaded.	Mary Ellen/8/9/2006
	4	Please explain how the input AC power was varied from 85% to 115% and	No change in output power level was	Mary Ellen/8/9/2006
		the power output monitored.	observed when the AC input power	
			to the product was varied from 93.5 to 126.5 VAC (+/- 15%).	

The items indicated above must be submitted before processing can continue on the referenced application. Failure to provide the requested information within 60 days may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1106.