Mike Kuo

From: daphne.liang [daphne.liang@tw.ccsemc.com]

Sent: Thursday, December 29, 2005 2:55 AM

To: Mike Kuo
Cc: lucy.tsai

Subject: Re GRE: Re FW: J-LINK CO., LTD., FCC ID: TVT-GR-01, Assessment NO.: AN05T5383, Notice#1-

Updated(1229)

Attachments: GR-01_Report(RP1)1229-1.pdf; GR-01_Setup photo(1229).pdf

Dear Mike:

Sorry for trouble you again. Please find the attached for updated(1229) test report page 10-12 and setup photo.

If still have any problems, please connect with me, thank you for your support.

BEST REGARDS

Daphne Liang / 梁鈺如 12/29/2005

Certification Team Leader / R&D and Certification Dept.

Compliance Certification Services Inc.

Rm. 258, Bldg. 17, No. 195, Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.

Tel: 886-3-5910068 EXT: 502

Fax: 886-3-5825720

E-mail: daphne.liang@tw.ccsemc.com

URL: http://www.ccsemc.com.tw

lucy.tsai

收件人: daphne_liang/ccsemc, vanessa.tsai/ccsemc@ccsemc 蔡文君

副本抄送:

主旨: RE: Re : FW: J-LINK CO., LTD. , FCC ID: TVT-GR-01 , Assessment NO.: ANO5T5383, Notice#1-Updated(1227)

2005/12/28 09:44

----- 轉呈者 lucy.tsai/ccsemc 於 2005/12/28 09:37 AM -----

"Mike Kuo"

<mike.kuo@ccsemc.com> 收件人: "daphne.liang" <daphne.liang@tw.ccsemc.com>

副本抄送: "application" <application@tw.ccsemc.com>, "lucy.tsai" <lucy.tsai@tw.ccsemc.com>

2005/12/28 03:12 AM 主旨: RE: Re : FW: J-LINK CO., LTD. , FCC ID: TVT-GR-01 , Assessment NO.: ANO5T5383, Notice#1-Updated

(1227)

Hi Daphne:

Based upon the bandwidth plots, I do not think the measurement was made with audio modulation. Please submit 20 BW plots with iPod tuned to max. volume and measure low, middle and high 20 dB. The spectrum plots must show two traces, one with audio modulation and one without audio modulation.

Best Regards

Mike Kuo Compliance Certification Services 561F Monterey Road Morgan Hill CA 95037 Tel: (408)463-0885 x: 105

e-mail:mike.kuo@ccsemc.com http://www.ccsemc.com

Fax: (408)463-0888

From: daphne.liang [mailto:daphne.liang@tw.ccsemc.com]

Sent: Monday, December 26, 2005 8:09 PM

To: Mike Kuo

Cc: application; lucy.tsai

Subject: Re: FW: J-LINK CO., LTD., FCC ID: TVT-GR-01, Assessment NO.: AN05T5383, Notice#1-Updated(1227)

Dear Mike:

Thank you for your e-mail. Please see the belowing reply and find the updated(1227) files. If still have any problems, please connect with me, thank you for your support and Happy New Year!!

BEST REGARDS

Daphne Liang / 梁如 12/27/2005 Certification Team Leader / R&D and Certification Dept.

Compliance Certification Services Inc. Rm.258, Bldg.17, No.195, Sec.4, Chung Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.

Tel: 886-3-5910068 EXT: 502

Fax: 886-3-5825720

E-mail: daphne.liang@tw.ccsemc.com

URL: http://www.ccsemc.com.tw

"Mike Kuo" <mike.kuo@ccsemc.com>

收件人: <Daphne.liang@tw.ccsemc.com>, "application" <application@tw.ccsemc.com>

副本抄送:

2005/12/24 09:46 主旨: FW: J-LINK CO., LTD., FCC ID: TVT-GR-01, Assessment NO.: ANOST5383, Notice#1

Question #1: Please explain in detail on the operating condition during the final tests. Per ANSI C63.4 section 13.1.1.1 applied modulation, the device equipped with any input connector to for external modulation, then the device must be tested with modulation on. For this FM transmitter, the purpose for the transmitter is to modulate audio signal to car radio. In this test report, no information is provided to address modulation condition.

Ans: Sorry for confused you. Please find the updated test report(1227) with add some datas in

Page 9, Page 19-21.

And also add the new photo with iPod.

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.