CETECOM ICT Services GmbH

Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075

CETECOM

Test report no.: 2-4189-01-04/05 Date: 2006-02-14 Page 90 of 107

5 Photographs of Test Set-up

Photo 1: Radiated Emissions S45



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory Phone: +49 (0

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075

CETECOM

Test report no.: 2-4189-01-04/05 Page 91 of 107 Date: 2006-02-14

E45



CETECOM ICT Services GmbH


Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075

CETECOM

Test report no.: 2-4189-01-04/05 Date: 2006-02-14 Page 92 of 107

Photo 2: Radiated Emissions S45



CETECOM ICT Services GmbH


Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075

CETECOM

Test report no.: 2-4189-01-04/05 Date: 2006-02-14 Page 93 of 107

E45



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken Phone: +49 (

RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075

CETECOM

Test report no.: 2-4189-01-04/05 Page 94 of 107 Date: 2006-02-14

Photo 3: Conducted Emissions S45



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory Phone: +49 (0

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075

CETECOM

Page 95 of 107 Test report no.: 2-4189-01-04/05 Date: 2006-02-14

E45

