Hi Tim,

Please find the replies regarding to your last comments below, thanks!!

- 1. The non-compliance between cover letters and the Form731 is fixed, please find the updated cover letters just been uploaded
- 2. Please give me the idea if the applicant put the statement of the 15.19(3) into an individual label next to the current one, since the size of the current label is not enough and that is already had the molded area on the outer housing of the EUT for the labelling makes the applicant not willing to change the current label. Please comment.
- 3. Please find the TX schematics uploaded.