

Report No. : FA260551

Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: TWG-SDCMSD40NBT

Page Number : D1 of D2
Report Issued Date : Aug. 16, 2012
Report Version : Rev. 01

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: TWG-SDCMSD40NBT

Page Number : D2 of D2
Report Issued Date : Aug. 16, 2012
Report Version : Rev. 01

Report No. : FA260551



Report No. : FA260551

Appendix E. Test Setup Photos



Front of the DUT with Phantom 0 cm Gap

Back of the DUT with Phantom 0 cm Gap



Left of the DUT with Phantom 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: TWG-SDCMSD40NBT

Page Number : E1 of E1 Report Issued Date: Aug.16, 2012

Report Version : Rev. 01