1. External Photographs of EUT

Model Name: NX 594

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 1 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 2 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 3 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 4 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 5 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2


Page Number : 6 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

2. Photographs of Accessories

Model Name: NX 594

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 7 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 8 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 9 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 10 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

3. Internal Photographs of EUT

Model Name: NX 594

Report No.: EP8O1411-02


(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 11 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 12 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02




Report No.: EP8O1411-02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 13 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP801411-02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 14 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02


(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 15 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

Report No.: EP801411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 16 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP801411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 17 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP801411-02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 18 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 19 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP801411-02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 20 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02



SPORTON INTERNATIONAL INC.

01

30

50

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 21 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

10

50

30

40

09


09


08

06

04


Report No.: EP8O1411-02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 22 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02


Report No.: EP801411-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 23 of 26
Issued Date : Dec. 03, 2008
Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 24 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02

(Radio module: 19-25133-842 in NX4 Alarm panel: NX4)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2

Page Number : 25 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02

Report No.: EP8O1411-02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV19251390X2 IC ID: 6322A-19251390X2 Page Number : 26 of 26 Issued Date : Dec. 03, 2008 Report Version : Rev. 02