




Report No.: FD8O1413

## **Appendix B. Setup Photographs**

## <Conducted Emission>



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV192513384X Page Number : B1 of B4 Report Issued Date: Nov. 11, 2008 Report Version : Rev. 01





Report No.: FD8O1413



Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV192513384X Page Number : B2 of B4
Report Issued Date : Nov. 11, 2008
Report Version : Rev. 01






Report No. : FD8O1413

## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV192513384X Page Number : B3 of B4
Report Issued Date : Nov. 11, 2008
Report Version : Rev. 01





Report No.: FD8O1413



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TWV192513384X Page Number : B4 of B4
Report Issued Date : Nov. 11, 2008
Report Version : Rev. 01