

21 May 2008

To whom it may concern,

We the undersigned, seek FCC and IC approval of a Class II Permissive Change for our Speedway RFID Reader, Impinj model number IPJ-R1000. The reason for the Class II change is the addition of one new antenna meant to operate with the reader. The reader operation, block diagram, schematics, label, equipment name, and photographs are unchanged. However, the nature of this change necessitates the need for RF testing to verify that the reader remains regulatory compliant.

The following antenna has been tested and added to the Speedway RFID Reader User Manual.

IPJ-A0310-USA

Threshold Antenna

The reader certification information is below.

FCC certification number: TWYIPJR1000 IC certification number: 6324A-IPJR1000

Sincerely, Ron Paulsen Vice President, Engineering Impini, Inc.