

4. Internal Photograph of the Host

Host: (Brand Name: UNICOM / Model Name: U-BPCIB000, U-BPCIB001)


Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 18 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 19 of 32 Report Issued Date : Jan. 25, 2017 Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 20 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01




Report No.: EP2D0508-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 21 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01




Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 22 of 32 Report Issued Date : Jan. 25, 2017 Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 23 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS

: 24 of 32 Page Number Report Issued Date : Jan. 25, 2017 Report Version : Rev. 01




Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 25 of 32 Report Issued Date : Jan. 25, 2017 Report Version : Rev. 01



Report No.: EP2D0508-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 26 of 32 Report Issued Date : Jan. 25, 2017 Report Version : Rev. 01

Report No.: EP2D0508-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 27 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 28 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 29 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 30 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 31 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 32 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01