



Appendix D. Product Photos





Report No.: FA020501-28







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : D1 of D1
Report Issued Date : Apr. 09, 2011
Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom of Laptop with Phantom 0 cm Gap (Sample 1)

Bottom of Laptop with Phantom 0 cm Gap (Sample 2)

Report No.: FA020501-28

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : E1 of E1 Report Issued Date: Apr. 09, 2011

Report Version : Rev. 01