





Photographs of EUT

Mode: Second source Mode


Config.1 Diversity – PCIE (Second source)














Config.1 Diversity – USB (Second source)



















Config. 2 Fixed – PCIE (Second source)














Config. 2 Fixed – USB (Second source)
















Report No.: 211949


Config. 3 Single - PCIE (Second source)















Config. 3 Single – USB (Second source)















Report No.: 211949


Mode: Main source Mode

Config.1 Diversity – PCIE (Main source)






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : 10 OF **18**ISSUED DATE : Apr. 13, 2012










Config.1 Diversity – USB (Main source)















Report No.: 211949

Config. 2 Fixed – PCIE (Main source)















Config. 2 Fixed – USB (Main source)




















Config. 3 Single - PCIE (Main source)











Config. 3 Single – USB (Main source)

