

Page Number


Report Version

: 25 of 44


: Rev. 01

Report Issued Date : May 19, 2017

Report No.: EP733003



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821CE IC: 6317A-RTL8821CE Page Number : 26 of 44
Report Issued Date : May 19, 2017
Report Version : Rev. 01



Report No.: EP733003


Page Number

Report Version


: 27 of 44

: Rev. 01


Report Issued Date : May 19, 2017



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821CE IC: 6317A-RTL8821CE



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821CE IC: 6317A-RTL8821CE Page Number : 29 of 44
Report Issued Date : May 19, 2017
Report Version : Rev. 01



Page Number


Report Version

: 30 of 44

: Rev. 01

Report Issued Date : May 19, 2017

Report No.: EP733003



Report No.: EP733003


Page Number

Report Version


: 31 of 44

: Rev. 01

Report Issued Date : May 19, 2017



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821CE IC: 6317A-RTL8821CE Page Number : 32 of 44
Report Issued Date : May 19, 2017
Report Version : Rev. 01



Report No.: EP733003


Page Number

Report Version

: 33 of 44

: Rev. 01

Report Issued Date : May 19, 2017



Page Number


Report Version

: 34 of 44

: Rev. 01

Report Issued Date : May 19, 2017

Report No.: EP733003




Report No.: EP733003

Page Number

: 35 of 44

Report Issued Date : May 19, 2017

Report Version : Rev. 01



Report No.: EP733003


Page Number

Report Version

: 36 of 44

: Rev. 01

Report Issued Date : May 19, 2017



Report No.: EP733003

Page Number

Report Version

: 37 of 44

: Rev. 01


Report Issued Date : May 19, 2017



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821CE IC: 6317A-RTL8821CE Page Number : 38 of 44
Report Issued Date : May 19, 2017

Report No.: EP733003

Report Version : Rev. 01



Report No.: EP733003


Page Number

Report Version

: 39 of 44

: Rev. 01

Report Issued Date : May 19, 2017



Report No.: EP733003


Page Number

Report Version

: 40 of 44

: Rev. 01

Report Issued Date : May 19, 2017



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821CE IC: 6317A-RTL8821CE Page Number : 41 of 44
Report Issued Date : May 19, 2017
Report Version : Rev. 01



Page Number


Report Version

: 42 of 44

: Rev. 01

Report Issued Date : May 19, 2017

Report No.: EP733003



Report No.: EP733003


Page Number

Report Version

: 43 of 44

: Rev. 01

Report Issued Date : May 19, 2017



Report No.: EP733003

Page Number

Report Version

: 44 of 44

: Rev. 01

Report Issued Date : May 19, 2017