


Report No.: FA332724-24

Appendix D. SAR Test Setup Photos

<Chain 1>








Back, Test Separation 0.5 cm




Right Side, Test Separation 0.5 cm



Left Side, Test Separation 0.5 cm



Top Side, Test Separation 0.5 cm



Bottom Side, Test Separation 0.5 cm

Page D1 of D3


TEL: 886-3-327-3456 / FAX: 886-3-328-4978

FCC ID: TX2RTL8192EEBT


Issued Date: May 14, 2015 Form version. : 150415



<Chain 1+2>









Report No. :FA332724-24


Back, Test Separation 0.5 cm




Right Side-1, Test Separation 0.5 cm



Right Side-2, Test Separation 0.5 cm



Left Side-1, Test Separation 0.5 cm




Left Side-2, Test Separation 0.5 cm

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

FCC ID: TX2RTL8192EEBT

Issued Date : May 14, 2015
Page D2 of D3
Form version. : 150415







Top Side, Test Separation 0.5 cm

Bottom Side, Test Separation 0.5 cm

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

FCC ID: TX2RTL8192EEBT Page D3 of D3 Form

Issued Date : May 14, 2015 Form version. : 150415