
## 1. Photograph of the EUT

EUT: 802.11b/g/n RTL8192EE Combo module (Brand Name: Realtek / Model Name: RTL8192EEBT)

Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 1 of 25
Report Issued Date : Apr. 25, 2014

EUT: 802.11b/g/n RTL8192EE Combo module (Brand Name: Realtek / Model Name: RTL8192EEBT)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 2 of 25 Report Issued Date : Apr. 25, 2014

Report Version

: Rev. 01

## 2. External Photograph of the Host

Host: Notebook (Brand Name: lenovo / Model Name: TP00066A)

Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 3 of 25 Report Issued Date : Apr. 25, 2014

: Rev. 01

Report Version



Report No.: EP421460-01

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 4 of 25 Report Issued Date : Apr. 25, 2014



Report No.: EP421460-01

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 5 of 25 Report Issued Date : Apr. 25, 2014 Report Version : Rev. 01



Host: Notebook (Brand Name: lenovo / Model Name: TP00066A)

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 6 of 25
Report Issued Date : Apr. 25, 2014
Report Version : Rev. 01



Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 7 of 25 Report Issued Date : Apr. 25, 2014



Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 8 of 25

Report Issued Date : Apr. 25, 2014 Report Version : Rev. 01



Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 9 of 25

Report Issued Date : Apr. 25, 2014
Report Version : Rev. 01



Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 10 of 25 Report Issued Date : Apr. 25, 2014



Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 11 of 25 Report Issued Date : Apr. 25, 2014 Report Version : Rev. 01

## 3. Photograph of Accessory for the Host

Host: Notebook (Brand Name: lenovo / Model Name: TP00066A)

Report No.: EP421460-01

**List of Accessory for Host (Notebook Computer):** 

Specification of Accessory		
AC Adapter 1	Brand Name	Lenovo
	Model Name	ADLX45NLC3A
AC Adapter 2	Brand Name	Lenovo
	Model Name	ADLX45NDC3A
Battery 1	Brand Name	Lenovo
	Model Name	45N1748
Battery 2	Brand Name	Lenovo
	Model Name	45N1750

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 12 of 25
Report Issued Date : Apr. 25, 2014
Report Version : Rev. 01

Report No.: EP421460-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 13 of 25
Report Issued Date : Apr. 25, 2014

Host: Notebook (Brand Name: lenovo / Model Name: TP00066A)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 14 of 25
Report Issued Date : Apr. 25, 2014
Report Version : Rev. 01

Host: Notebook (Brand Name: lenovo / Model Name: TP00066A)

AC Adapter 2

| The Control of Contro

 ${\it SPORTON\,INTERNATIONAL\,INC}.$ 

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 15 of 25
Report Issued Date : Apr. 25, 2014





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 16 of 25
Report Issued Date : Apr. 25, 2014
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : 17 of 25

Report Issued Date : Apr. 25, 2014