



Report No. : FA342603-03


Appendix D. SAR Test Setup Photos




Top Side, Test Separation 0.5cm




Bottom, Test Separation 0.5cm




Front, Test Separation 0.5cm



Back, Test Separation 0.5cm



Right Side, Test Separation 0.5cm



Left Side, Test Separation 0.5cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8821AE Page Number : D1 of D1
Report Issued Date : Jul. 26, 2013
Report Version : Rev. 01