

### Report No.: FR021101


# Appendix B. Setup Photographs

## <Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: TX2-RTL8191SE Page Number : B1 of B5
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01





Report No. : FR021101



Side View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: TX2-RTL8191SE Page Number : B2 of B5
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01



#### <Radiated Emission>

#### **Laptop Mode**



Front View



Rear View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: TX2-RTL8191SE Page Number : B3 of B5
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01

Report No.: FR021101




Report No.: FR021101



Remote View

#### **Tablet Mode**



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: TX2-RTL8191SE Page Number : B4 of B5 Report Issued Date : Mar. 02, 2010 Report Version : Rev. 01






Report No.: FR021101

Rear View





Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: TX2-RTL8191SE Page Number : B5 of B5
Report Issued Date : Mar. 02, 2010
Report Version : Rev. 01