

Appendix D. Product Photos

<Sample 1>





Report No.: FA080215-05







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8188CEB8 Page Number : D1 of D2
Report Issued Date : Mar. 23, 2011
Report Version : Rev. 01






<Sample 2>





Report No.: FA080215-05







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8188CEB8 Page Number : D2 of D2
Report Issued Date : Mar. 23, 2011
Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom of Laptop with Phantom 0 cm Gap (Sample 1)



Report No.: FA080215-05

Bottom of Laptop with Phantom 0 cm Gap (Sample 2)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8188CEB8 Page Number : E1 of E1
Report Issued Date : Mar. 23, 2011
Report Version : Rev. 01