


Appendix D. Product Photos

Laptop: Trade Name: Lenovo / Model Name: X100e




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE IC: 6317A-RTL8188CE Page Number : D1 of D2
Report Issued Date : Jul. 15, 2010
Report Version : Rev. 02

Report No.: FA020501-05

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE IC: 6317A-RTL8188CE Page Number : D2 of D2
Report Issued Date : Jul. 15, 2010
Report Version : Rev. 02

Report No.: FA020501-05



Appendix E. Test Setup Photos



Bottom of the Laptop with Phantom 0 cm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE IC: 6317A-RTL8188CE Page Number : E1 of E1
Report Issued Date : Jul. 15, 2010
Report Version : Rev. 02

Report No.: FA020501-05