


Appendix B. Setup Photographs


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BE Page Number : B1 of B1
Report Issued Date : Feb. 03, 2015
Report Version : Rev. 01

Report No.: FR510105A

Report Template No.: BU5-FR15CBT Version 1.0