Report No.: 0601332


DVD Playing mode (Modulating On) AC Mains

Tested By:Hong, Report No.:0601332 Scan Settings (1 Range)

|----- Frequencies --------||-----Receiver Settings ------Step IF BW Detector M-Time Atten Preamp OpRge
5k 10k PK+AV 10ms AUTO LN OFF 60dB Start Stop 150k 30M

Transducer No. Start Stop Name
1 15 9k 30M EW0090
21 9k 30M EW0698 Final Measurement: x QP / + AV Meas Time: 1 s

Subranges: 16 Acc Margin: 20dB





Report No.: 0601332

DVD Playing mode (Modulating On) AC Mains

Tested By:Hong, Report No.:0601332

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings ------

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge 150k 30M 5k 10k PK+AV 10ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

0.15000 41.6 66.0

Frequency AV Level AV Limit

MHz dBuV dBuV

no Results

* limit exceeded