


page 1 of 3

ANNEX B INTERNAL PHOTOS



123441_14.JPG: WLAN module, shielding removed

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F123441E1

 Date of issue:
 18 October 2012
 Order No.:
 12-113441



page 2 of 3

ANNEX B INTERNAL PHOTOS



123441_15.JPG: WLAN module with shielding and temporary antenna connectors

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F123441E1

 Date of issue:
 18 October 2012
 Order No.:
 12-113441



page 3 of 3

ANNEX B INTERNAL PHOTOS



123441_18.JPG: WLAN module shielded and internal antennae

Test Report No.: F123441E1 Order No.: 12-113441

Examiner: Manuel BASTERT Date of issue: 18 October 2012